

PRODUCT FAULT NOTICE

DATE: 12TH MAY 2023

SUBJECT: CRESTRON HOME DRIVER

AFFECTED PRODUCT:


- neo:X+ (P8-HDBT2-U-FFMJ1210; P8-HDBT2-U-FFMJ1210-S)
- neo:XMR (P8-HDBT2-U-FFMJ108-S)
- neo:XSR (P8-HDBT2-L-FFMJ66-S)
- neo:8A (P8-HDBT-L-FFMN810)
- neo:6A (P8-HDBT-L-FFMN68A)
- neo:4Pro (P8-HDBT-L-FFMS44-22)

FAULT DESCRIPTION:

Dear Valued Customer,

We have been informed that the latest CrestronHome Software update version 3.19 has a known issue with products using HTTP. This issue affects several products, including some Pulse-Eight matrices. Rebooting the control system fixes the issue temporarily although the problem is likely to reappear after a few days or weeks, when another reboot might be necessary.

Crestron is aware of the problem, and is expected to resolve the known issue in version 3.20 when released. Please refer to the Crestron Home Software Update, 3.019.0156 Release Notes:



Picture 1: Warning taken from Crestron Home Software Update 3.019.0156, Release Note

For more information on this issue, or when the CrestronHome Software update 3.20 will be released, please contact your Crestron representative directly.

PULSE-EIGHT CONTACT INFORMATION:

Pulse-Eight Customer Support
Email: support@pulse-eight.com
Tel: United Kingdom: +44 (0)1202 413 610
USA: (858) 748-8250
Australia: +61 3 83761230